



MICHAEL R. STYLER Executive Director JOHN R. BAZA
Division Director

Inspection Report Minerals Regulatory Program Penert Data: Sentember 20, 2006

Supervisor And

Report Date: September 29, 2006

Mine Name: Esc	alante Silver Mine
Operator Name:	Hecla mining Company
	Paul Glader

6500 Mineral Drive Suite 200 Coeur D'alene, Idaho 83815-9408

Inspector(s): Doug Jensen Other Participants: None Mine Status: Reclaimed Permit number: M/021/004 Date: September 14, 2006

Time: 5:25 PM

Weather: Cool

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds			
 Public Safety (shafts, adits, trash, signs, highwalls) Protection of Drainages / Erosion Control 			
4. Deleterious Material			
5. Roads (maintenance, surfacing, dust control, safety)			
6. Concurrent Reclamation			
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)			
8. Water Impoundments			
9. Soils			
10. Revegetation			
11. Air Quality			
12. Other			

Purpose of Inspection:

Inspected the site to assess revegetation success of seeding done on a reclaimed dump.

Directions to Site:

See previous inspection report.

Inspection Summary:

The area that was reseeded does show some vegetation success. Considering the time of year the planting does look pretty good. The vegetation was not sufficient to reach release criteria but this was the first full year for the seeding so may fill in more over the winter.

Conclusions and Recommendations:

I will take a biologist with me next spring to have the vegetation evaluated.

Inspector's Signature Library Jensen	Date:	9/29/06
		, ,

dj:pb

cc: Hecla Mining Company

Ed Ginouves, BLM, Cedar City FO UTU-67116 O:\M021-Iron\M0210004-Hecla\Inspection\09142006insp.doc

